## **Certificate of Analysis**

## **Client**

E&O Laboratories Ltd Burnhouse Bonnybridge Scotland FK4 2HH



Burnhouse, Bonnybridge Scotland, FK4 2HH Telephone: 01324 840404 Fax:01324 841314 Email: info@eolabs.com

Sample: PP3010 - Colorex Candida

**Batch Number:** 04157689

**Expiry Date:** 2021-11-22

**Date Received:** 2021-09-13

**Date Tested:** 2021-09-13

**Date of Issue:** 2021-09-16

Sample Condition: Satisfactory

Sample Number: 409081

Physical	Result	Specifications	Accredited Test Method
Sterility	Conforms	Within acceptable limits	ED/SOP/005 Visual check and growth assessment
,			following incubation for 3 days at 15-25°C and 37°C
Sterility sampling is performed in accordance with ISO 2859-1:1999*. The inspection level is $\geq$ 0.4% of the batch and the reject level $\leq$ 7 units depending on batch size.			
рН	6.3	6.1 +/- 0.2	ED/SOP/003 measurement by pH meter
Colour	Conforms	2-8 - 6-8 Straw	ED/SOP/009 by visual observation. Range measured using Pantone® 4 colour process guide
Fill Quantity	Conforms	18-22ml	ED/SOP/054 by gravimetric determination
Moisture	Conforms	95% +/- 3%	ED/SOP/053 with drying and gravimetric determination

## **Certificate of Analysis**

## **Client**

E&O Laboratories Ltd Burnhouse Bonnybridge Scotland FK4 2HH



Burnhouse, Bonnybridge Scotland, FK4 2HH Telephone: 01324 840404 Fax:01324 841314 Email: info@eolabs.com

**Sample:** PP3010 - Colorex Candida

Batch Number: 04157689

**Expiry Date:** 2021-11-22

**Date Received:** 2021-09-13

**Date Tested:** 2021-09-13

**Date of Issue:** 2021-09-16

Sample Condition: Satisfactory

Sample Number: 409081

All of the results on this certificate of analysis relate only to the samples submitted.

Test specifications are based on ISO 11133:2014/Amd/:2020 and internal product specifications \*Sterility sampling is outwith scope of accreditation.



**Douglas Cameron** 

**Technical Manager, E&O Laboratories Ltd**